

ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 25 JAN 00	3. CCR #: 00.0074	4. Rev: -	5. Tel: 925-0703	6. Rm #:	7. Org.
8. Title of Change: Baseline Clean-up						
9. Originator Signature/Date <i>Maryellen Corbett</i> 1/21/2000			10. Class II	11. Type: CCR	12. Need Date: 01/26/2000	
13. Office Manager Signature/Date <i>R.P. Nuge</i> 01/24/2000			14. Category of Change: Update Baseline		15. Priority: (If "Emergency" fill in Block 28). Routine	
16. Documentation/Drawings Impacted: 910-TDV-002; 920-TDV-002 ; 920-TDV-002; 920-TDE-002; 920-TDG-002 920-TDI-002; 920-TDN-002; 920-TDS-002; 920-TDP-002; 910-TDA			17. Schedule Impact:		18. CI(s) Affected:	
19. Release Affected: 5a & 5b			20. Date due to Customer:		21. Impl. Date:	
22. Estimated Cost: None						
23. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input checked="" type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
24. Description of Change: (use additional Sheets if necessary) During the CUT group meetings, it was identified that there were inconsistencies with some baseline configurations. These are identified on the following page.						
25. Proposed Solution: (use additional sheets if necessary) Correct the baseline changes red-lined in the baseline documents attached.						
26. Alternate Solution: (use additional sheets if necessary)						
27. Consequences if Change(s) are not approved: (use additional sheets if necessary) Audit will flag incorrect configurations.						
28. Justification for Emergency (If Block 15 is "Emergency"):						
29. Site(s) Affected: <i>Man</i> <input checked="" type="checkbox"/> EDF <input type="checkbox"/> Mini-DAAC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input checked="" type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
30. Board Comments:				31. Work Assigned To:		
32. EDF/REL2 CCB Chair (Sign/Date): <i>Man</i> 2-1-00		33. Disposition: <input checked="" type="checkbox"/> Approved <input type="checkbox"/> A/C <input type="checkbox"/> Disapproved <input type="checkbox"/> Fwd/ECS <input type="checkbox"/> Fwd/ESDIS		34. (TBD)		
35. M&O CCB Chair (Sign/Date): <i>Man</i> 1/31/00		36. Disposition: <input checked="" type="checkbox"/> Approved <input type="checkbox"/> A/C <input type="checkbox"/> Disapproved <input type="checkbox"/> Fwd/ECS <input type="checkbox"/> Fwd/ESDIS		37. CM Manager's Closure:		
38. ECS CCB Chair (Sign/Date):		39. Disposition: <input type="checkbox"/> Approved <input type="checkbox"/> A/C <input type="checkbox"/> Disapproved		40. CCR Closed Date:		

CM01 March 8, 1999

ECS/EDF/REL2 CCB

ORIGINAL

01-26-00A10:07 0402

ADDITIONAL SHEET

CCR #: 00.0074 Rev: - Originator: Maryellen Corbett

Telephone: 0703 Office: 2072C

Title of Change: Baseline Clean-up

1. On 5a & 5b, Change Purify baseline for Sun variant back to version 4.1. An emergency upgrade to 4.5.1 for Sun was done in the EDF. It was not intended to upgrade the baseline, as this requires a PSR. The upgrade is in progress, but has not been PSRd
2. Standardize naming conventions for Sybase SQL Server Monitor. SQL Monitor Server and SQL Monitor are identified in the current baselines. These are the same products. All variants should use the name "SQL Server Monitor Client/Server", as both the client & server portions are installed wherever Sybase SQL Server or Sybase Adaptive Server is installed. The 5b baseline identifies only a Sun variant. Variants are needed for SGI & HP. These variants should be added.
3. Correct the HW/SW map configurations relating to "SQL Server Monitor Client/Server". "SQL Server Monitor Client/Server" should only appear on hosts where Sybase Adaptive Server or Sybase SQL server is installed. It appears that SQL Monitor only is specified for HPs; both SQL Monitor and SQL Monitor Server is specified for SUNs; and neither is specified for SGI where a SQL Server implementation is identified. The known Sybase SQL Servers/Adaptive Servers are identified in attachments.
4. (5a only unless noted) Remove items associated with removal of AMASS IBM 3590 drives. With removal of the 3590 drives from the project, the following items should be removed from the baseline:
 - a. AML Mgt. Unit
 - b. DAS
 - c. Microcode for IBM 3590 (5a & 5b)
 - d. OS/2 Warp
 - e. OS2 Fixpak
5. Product vendor changes:
 - a. Commercial Secure Shell vendor Data Fellows changes to F-Secure Corporation
 - b. XRP-II vendor changes from HTG Corp. to SolutionBank
 - c. (5b only) IQ software vendor should be Sterling Software, not Sun Microsystems.
 - d. The vendor for Autosys products and DBVision is currently Computer Associates, Inc.. CA acquired Platinum.
 - e. The DCE Cell Manager vendor should be changed from Dascom to Tivoli Systems.
 - f. The vendor for Microcode for 9840 should be StorageTek not EMASS.
 - g. The vendor EMASS is now ADIC. Replacement of EMASS with ADIC.
6. Two IQ versions are specified: 5.5 & 5.5.01. Version 5.5.01 should be the only version.
7. (5B only) Remove EMACs version 20.3 as SGI/Sun variants, as this upgrade will not be planned at this time.
8. Remove comment from all Autosys, Autosys Xpert & Autosys Remote Agent entries. Comment relates to version not longer supported.
9. Remove comment from SQR entry (s). Comment is not appropriate to product - refers to another product.
10. Remove one of the Sybase Central entries: version 11.5. The only version that should be identified is 3.0.0.. This is a new product, not an upgrade.
11. Consolidate 2 heading entries for Firmware, MC and Firmware,MC. Only a space differentiates these. Only one heading entry is needed.(5a only)
12. Change the primary/secondary (P/S) indicator for m0mss16 & m0mss15. m0mss16 should be designaed as the Primary (P). m0mss15 should be designated as the secondary.
13. Remove the Function Designation "iFOR/ls License Server" from l0msh03 and t1msh01. Product removed from baseline.